

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	3	(synchronous adj (motor adj generator)) and ((rotor adj position) near2 extract\$6)	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:56
2	BRS	L2	60	(synchronous adj2 motor) and ((rotor adj position) with (phase adj voltage))	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:22
3	BRS	L3	7	2 and filter and ((two adj2 phase) with (quadrature or transform\$6))	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:23
4	BRS	L4	4	3 not 1	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:32

	Comments	Error Definition	Errors
1			
2			
3			
4			

	Type	L #	Hits	Search Text	DBs	Time Stamp
5	BRS	L5	3	"6809496"	US-PGPUB; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:34
6	BRS	L6	2	5 and (position)	US-PGPUB; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:41
7	BRS	L7	10	(synchronous adj2 motor) and (position with (emulat\$6 or imitat\$6))	US-PGPUB; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:45
8	BRS	L8	8	7 not 5	US-PGPUB; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:45

	Comments	Error Definition	Errors
5			
6			
7			
8			

	Type	L #	Hits	Search Text	DBs	Time Stamp
9	BRS	L9	93	(synchronous adj2 (machine or (motor adj generator))) and (rotor adj (speed or velocity)) and (stator with (exciter or excitat\$6))	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:27
10	BRS	L10	23	(9 not (anghel et "al."))	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:39
11	BRS	L11	70	9 not 10	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 12:59
12	BRS	L12	6	9 and (position same (filter near6 bandpass)) and excit\$6	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:40

	Comments	Error Definition	Errors
9			
10			
11			
12			

	Type	L #	Hits	Search Text	DBs	Time Stamp
13	BRS	L13	89	(9 not (anghel.in.))	US- PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:39
14	BRS	L14	2	13 and (position same (filter near6 bandpass)) and excit\$6	US- PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:42
15	BRS	L15	0	14 and ((bandpass adj filter) with (stator adj (winding or coil))) and ((phase near3 voltage) with (time or period or position)) and excitation	US- PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:47
16	BRS	L16	91	318/712.ccls.	US- PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:47

	Comments	Error Definition	Errors
13			
14			
15			
16			

	Type	L #	Hits	Search Text	DBs	Time Stamp
17	BRS	L17	0	16 and ((bandpass adj filter) with (stator adj (winding or coil))) and ((phase near3 voltage) with (time or period or position)) and excitation	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:47
18	BRS	L18	112	318/715.ccls.	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:48
19	BRS	L19	1	18 and ((bandpass adj filter) with (stator adj (winding or coil))) and ((phase near3 voltage) with (time or period or position)) and excitation	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:48
20	BRS	L20	142	318/716.ccls.	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:48

	Comments	Error Definition	Errors
17			
18			
19			
20			

	Type	L #	Hits	Search Text	DBs	Time Stamp
21	BRS	L21	0	20 and ((bandpass adj filter) with (stator adj (winding or coil))) and ((phase near3 voltage) with (time or period or position)) and excitation	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:48
22	BRS	L22	926	318/807.ccls.	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:48
23	BRS	L23	0	22 and ((bandpass adj filter) with (stator adj (winding or coil))) and ((phase near3 voltage) with (time or period or position)) and excitation	US-PGPUB ; USPAT; EPO; JPO; DERWE NT	2005/10/31 13:48

	Comments	Error Definition	Errors
21			
22			
23			